



Source : EPD Website

Figure 4.1

Typical Details of Impermeable Liner at SENT Landfill