ANNEX E3 EVENT AND ACTION PLAN FOR NOISE MONITORING

ANNEX E3 EVENT AND ACTION PLAN FOR OPERATIONAL NOISE MONITORING

Event	Action		
	ET	**IEC**	**Contractor**
Action Level	• Identify the source(s) and investigate the cause(s) of exceedance and complaint • Prepare Notification of Exceedance within 24 hours • Inform Contractor, IEC and Project Proponent whether the cause of exceedance is due to the Project • Discuss with Contractor and IEC for remedial measures required • Ensure remedial measures are properly implemented • Have additional monitoring if exceedance is due to the Project. If exceedance stops, cease additional monitoring	• Verify the Notification of Exceedance • Check monitoring data submitted by ET • Discuss with ET and Contractor on proposed remedial measures • Review proposals on remedial measures • Audit the implementation of the remedial measures • Audit the effectiveness of the implemented remedial measures	• Submit proposals for remedial measures to IEC • Implement the agreed proposals

	Action		
Event	**ET**	**IEC**	**Contractor**
Limit Level	• Identify the source(s) and investigate the cause(s) of exceedance and complaint • Prepare Notification of Exceedance within 24 hours • Inform Contractor, IEC, Project Proponent and EPD whether the cause of exceedance is due to the Project • Analyse the operation of SENTX and investigate the causes of exceedance • Provide interim report to Contractor, IEC, Project Proponent and EPD the causes of the exceedances • Discuss with Contractor and IEC for remedial measures required • Ensure remedial measures are properly implemented • Report the remedial measures implemented and the additional monitoring results to Contactor, IEC, Project Proponent and EPD • Have additional monitoring if exceedance is due to the Project. If exceedance stops, cease additional monitoring	• Verify the Notification of Exceedance • Check monitoring data submitted by ET • Discuss with ET and Contractor on proposed remedial measures • Review proposals on remedial measures • Audit the implementation of the remedial measures • Audit the effectiveness of the implemented remedial measures	• Take immediate measures to avoid further exceedance • Submit proposals for remedial measures to IEC within 3 working days of notification • Implement the agreed proposals • Resubmit proposals if problem still not under control • Stop the relevant activity of works as determined by the Project Proponent until the exceedance is abated

ERM