



ANNEX F2

EVENT AND ACTION PLAN FOR WATER QUALITY MONITORING

ANNEX F2 EVENT AND ACTION PLAN FOR WATER QUALITY MONITORING DURING OPERATION/ RESTORATION PHASE

| Action | | | |
|--|---|--|--|
| Event | ET | IEC | Contractor |
| Exceedance of Limit Level for surface water monitoring | <ul style="list-style-type: none"> Identify source(s) of impact and investigate the cause(s) of exceedance Prepare Notification of Exceedance within 24 hours Inform Contractor, IEC, Project Proponent and EPD (EIAO Authority) whether the cause of exceedance is due to the Project Discuss with Contractor and IEC for remedial measures required Ensure remedial measures are properly implemented Repeat measurement to confirm finding if exceedance is due to the Project Increase monitoring frequency to weekly if exceedance is due to the Project until no exceedance of Limit Level | <ul style="list-style-type: none"> Verify the Notification of Exceedance Check monitoring data submitted by ET Check Contractor's working methods Discuss with ET and Contractor on proposed remedial measures Review proposals on remedial measures Audit the implementation of the remedial measures Audit the effectiveness of the implemented remedial measures | <ul style="list-style-type: none"> Take immediate action to avoid further exceedance Submit proposals for remedial measures to IEC Implement the agreed proposals Amend proposal if appropriate |
| Exceedance of Limit Level for groundwater monitoring | <ul style="list-style-type: none"> Identify source(s) of impact and investigate the cause(s) of exceedance Prepare Notification of Exceedance within 24 hours Inform Contractor, IEC, Project Proponent and EPD (EIAO Authority) whether the cause of exceedance is due to the Project Discuss with Contractor and IEC for remedial measures required Ensure remedial measures are properly implemented | <ul style="list-style-type: none"> Verify the Notification of Exceedance Check monitoring data submitted by ET Check Contractor's working methods Discuss with ET and Contractor on proposed remedial measures Review proposals on remedial measures Audit the implementation of the remedial measures Audit the effectiveness of the implemented remedial measures | <ul style="list-style-type: none"> Divert groundwater collected at the collection sumps to the leachate treatment plant Submit proposals for remedial measures to IEC Rectify any unacceptable practice or design Amend working methods as required Implement amended working methods, if necessary |

| Action | | | |
|--|--|--|---|
| Event | ET | IEC | Contractor |
| | <ul style="list-style-type: none"> • Repeat measurement to confirm finding if exceedance is due to the Project • Increase monitoring frequency to weekly if exceedance is due to the Project until no exceedance of Limit Level | | |
| Exceedance of Limit Level for leachate level | <ul style="list-style-type: none"> • Investigate the cause(s) of exceedance • Prepare Notification of Exceedance within 24 hours • Inform Contractor, IEC, Project Proponent and EPD (EIAO Authority) whether the cause of exceedance is due to the Project • Discuss with Contractor and IEC for remedial measures required • Ensure remedial measures are properly implemented | <ul style="list-style-type: none"> • Verify the Notification of Exceedance • Check with Contractor on the operating activities and performance of the leachate collection system • Discuss with ET and Contractor on proposed remedial measures • Review proposals on remedial measures • Audit the implementation of the remedial measures • Audit the effectiveness of the implemented remedial measures | <ul style="list-style-type: none"> • Check the performance of the leachate collection system • Rectify any unacceptable practice; • Amend leachate collection design if required • Implement amended leachate collection system, if necessary |
| Exceedance of Limit Level of effluent discharge from LTP | <ul style="list-style-type: none"> • Investigate the cause(s) of exceedance • Prepare Notification of Exceedance within 24 hours • Inform Contractor, IEC, Project Proponent and EPD (EIAO Authority) whether the cause of exceedance is due to the Project • Discuss with Contractor and IEC for remedial measures required • Ensure remedial measures are properly implemented • Repeat measurement to confirm finding if exceedance is due to the Project | <ul style="list-style-type: none"> • Verify the Notification of Exceedance • Check with Contractor on the operation performance of the LTP • Discuss with ET and Contractor on proposed remedial measures • Review proposals on remedial measures • Audit the implementation of the remedial measures • Audit the effectiveness of the implemented remedial measures | <ul style="list-style-type: none"> • Rectify any unacceptable practice; • Carry out remedial measures or amend design as required • Implement amended design, if necessary |

| Action | | | |
|---------------|--|------------|-------------------|
| Event | ET | IEC | Contractor |
| | <ul style="list-style-type: none"> • Increase monitoring frequency to weekly until no exceedance of Limit Level | | |