Annex D8

Investigation Reports of Environmental Quality Limit Exceedance

| Project | South East New Territories (SENT) Landfill Extension |
|-----------------------------------|--|
| Date | 13 April 2023 |
| Time | 8:00 (13 April 2023) – 8:00 (14 April 2023) |
| Monitoring Location | AM1 |
| Parameter | 24-hour Total Suspended Particulates (TSP) |
| Action / Limit Levels | Action level: >260 μ g/ m ³ |
| | Limit level: >260 μ g/m ³ |
| Measured Level | 365 μg / m ³ |
| Possible reason | From the meteorological data obtained from the SENTX on-site meteorological monitoring station, a predominantly east- southeasterly to easterly wind with highest wind speed 3.2 m/s was recorded on 13 and 14 April 2023 during the sampling event. On 13 April 2023, dust and traffic emission from the SENT landfill in vicinity and located at the east of dust monitoring location AM1 were observed. The sample taken at AM1 on the day might not represent the operation dust emission from SENTX. In addition, no SENTX works which may lead to potential dust |
| | emission was conducted in the vicinity of dust monitoring location AM1 on the sampling day based on on-site observations and construction and operation activities as described by the Contractor. Environmental deficiency was not observed during the weekly site inspection on 13 April 2023. The Contractor has implemented the dust control and mitigation measures recommended in the updated EM&A Manual. |
| | In accordance with Table 3.8b of the updated EM&A Manual, repeat measurement was conducted on 19 April 2023 to confirm findings. 24-hour TSP level of $142 \mu g/m^3$ (below Action and Limit Levels) was measured during the sampling event, which demonstrate no consecutive dust impact at AM1. |
| | Due to presence of the influencing factor from the SENT landfill and no potential source from the Project-related activities in the vicinity of AM1 which may lead to the high TSP level was identified, there is no adequate evidence showing that the TSP exceedance at AM1 was deemed to Project-related activities. |
| Action Taken / Action to be Taken | Examination of environmental performance of the Project will be continued during the weekly inspections. The Contractor is reminded to implement relevant and appropriate mitigation measures according to the updated EM&A Manual to avoid any exceedance of the Action/Limit Level. |
| | The Contractor is also reminded to implement additional dust |

Investigation Report of Environmental Quality Limit Exceedance

| | | control measures to minimize the dust impact from SENT Landfill to the SENTX boundary. |
|--------------|---------------|--|
| Remarks | | - |
| Prepared by: | Abbey Lau | |
| Designation: | Environmenta | 1 Team |
| Date: | 28 April 2023 | |