

Annex D6

## Odour Monitoring Results

**Table D6.1 Odour Monitoring Results**

Date	Weather	Location	Time	Temperature (°C)	Wind Speed (m/s)	Wind Direction	From Project Site	Odour Intensity	Odour Characteristic	Possible Source	Remarks
24-Nov-22	Shower	OP1	15:00	21.9	12.3	S	No	0	N/A	N/A	N/A
24-Nov-22	Shower	OP2	15:04	21.7	4.0	S	No	0	N/A	N/A	N/A
24-Nov-22	Shower	OP3	15:07	21.9	0.7	N	Yes	0	N/A	N/A	N/A
24-Nov-22	Shower	OP4	15:09	21.9	4.8	E	No	0	N/A	N/A	N/A
24-Nov-22	Shower	OP5	15:11	22.2	2.3	E	No	0	N/A	N/A	N/A
24-Nov-22	Shower	OP6	15:12	22.5	7.6	N	No	0	N/A	N/A	N/A
24-Nov-22	Shower	OP7	15:14	22.0	4.3	N	No	0	N/A	N/A	N/A
24-Nov-22	Shower	OP8	15:17	22.0	3.5	E	Yes	1	N/A	Tipping area	Waste
24-Nov-22	Shower	OP9	15:22	21.6	1.0	E	Yes	0	N/A	N/A	N/A
24-Nov-22	Shower	OP10	15:24	21.7	1.3	E	Yes	0	N/A	N/A	N/A
24-Nov-22	Shower	OP11	15:38	21.4	3.5	E	No	0	N/A	N/A	N/A
24-Nov-22	Shower	OP12	15:36	21.4	2.3	E	No	0	N/A	N/A	N/A
24-Nov-22	Shower	OP13	15:34	21.1	4.7	E	No	0	N/A	N/A	N/A
24-Nov-22	Shower	OP14	15:31	21.2	1.5	N	No	0	N/A	N/A	N/A
24-Nov-22	Shower	OP15	15:46	21.2	1.7	E	No	0	N/A	N/A	N/A
24-Nov-22	Shower	OP16	15:51	21.5	1.8	E	No	0	N/A	N/A	N/A
24-Nov-22	Shower	OP17	15:53	21.4	1.2	NE	No	0	N/A	N/A	N/A