

Annex D6

Odour Monitoring Results

Table D6.1 Odour Monitoring Results

Date	Weather	Location	Time	Temperature (°C)	Wind Speed (m/s)	Wind Direction	From Project Site	Odour Intensity	Odour Characteristic	Possible Source	Remarks
26-Jan-23	Fine	OP1	14:37	20.8	5.5	N	Yes	0	N/A	N/A	N/A
26-Jan-23	Fine	OP2	14:31	17.8	5.2	N	Yes	0	N/A	N/A	N/A
26-Jan-23	Fine	OP3	14:43	20.5	1.9	W	No	0	N/A	N/A	N/A
26-Jan-23	Fine	OP4	14:45	20.3	1.6	E	Yes	1	Leachate	Pump truck	N/A
26-Jan-23	Fine	OP5	14:49	20.3	0.0	N/A	N/A	0	N/A	N/A	N/A
26-Jan-23	Fine	OP6	14:51	18.0	4.9	NE	Yes	0	N/A	N/A	N/A
26-Jan-23	Fine	OP7	14:53	17.9	1.3	N	No	0	N/A	N/A	N/A
26-Jan-23	Fine	OP8	14:56	21.9	0.0	N/A	N/A	0	N/A	N/A	N/A
26-Jan-23	Fine	OP9	15:00	19.8	1.1	SE	Yes	0	N/A	N/A	N/A
26-Jan-23	Fine	OP10	15:02	22.3	0.0	N/A	N/A	0	N/A	N/A	N/A
26-Jan-23	Fine	OP11	15:16	21.2	4.8	E	No	0	N/A	N/A	N/A
26-Jan-23	Fine	OP12	15:13	21.4	3.7	E	No	0	N/A	N/A	N/A
26-Jan-23	Fine	OP13	15:11	21.5	0.0	N/A	N/A	0	N/A	N/A	N/A
26-Jan-23	Fine	OP14	15:07	22.4	2.0	NW	Yes	0	N/A	N/A	N/A
26-Jan-23	Fine	OP15	15:29	17.8	3.7	N	Yes	0	N/A	N/A	N/A
26-Jan-23	Fine	OP16	15:32	17.6	4.0	NE	Yes	0	N/A	N/A	N/A
26-Jan-23	Fine	OP17	15:34	17.5	1.8	W	Yes	0	N/A	N/A	N/A