

Annex D6

## Odour Monitoring Results

**Table D6.1 Odour Monitoring Results**

Date	Weather	Location	Time	Temperature (°C)	Wind Speed (m/s)	Wind Direction	From Project Site	Odour Intensity	Odour Characteristic	Possible Source	Remarks
27-Jul-23	Sunny	OP1	14:16	33.1	0.6	N	Y	0	N/A	N/A	N/A
27-Jul-23	Sunny	OP2	14:20	33.9	4.5	S	N	0	N/A	N/A	N/A
27-Jul-23	Sunny	OP3	14:22	34.3	0.9	SW	N	0	N/A	N/A	N/A
27-Jul-23	Sunny	OP4	14:24	34.9	3.0	S	N	0	N/A	N/A	N/A
27-Jul-23	Sunny	OP5	14:26	35.4	2.8	NW	N	0	N/A	N/A	N/A
27-Jul-23	Sunny	OP6	14:28	36.2	3.1	S	N	0	N/A	N/A	N/A
27-Jul-23	Sunny	OP7	14:29	35.1	5.0	S	N	0	N/A	N/A	N/A
27-Jul-23	Sunny	OP8	14:32	34.5	4.7	S	N	0	N/A	N/A	N/A
27-Jul-23	Sunny	OP9	14:36	35.6	1.9	E	Y	0	N/A	N/A	N/A
27-Jul-23	Sunny	OP10	14:37	36.9	0.9	SE	N	0	N/A	N/A	N/A
27-Jul-23	Sunny	OP11	14:49	35.5	1.9	SW	Y	0	N/A	N/A	N/A
27-Jul-23	Sunny	OP12	14:48	34.5	1.8	SW	Y	0	N/A	N/A	N/A
27-Jul-23	Sunny	OP13	14:45	35.6	1.7	SW	Y	0	N/A	N/A	N/A
27-Jul-23	Sunny	OP14	14:43	35.7	0.0	N/A	N/A	0	N/A	N/A	N/A
27-Jul-23	Sunny	OP15	14:58	34.2	0.0	N/A	N/A	0	N/A	N/A	N/A
27-Jul-23	Sunny	OP16	15:02	34.2	2.6	NE	Y	1	Waste	Tipping area	N/A
27-Jul-23	Sunny	OP17	15:04	34.6	0.0	N/A	N/A	0	N/A	N/A	N/A