

Annex D6

Odour Monitoring Results

Table D6.1 Odour Monitoring Results

Date	Weather	Location	Time	Temperature (°C)	Wind Speed (m/s)	Wind Direction	From Project Site	Odour Intensity	Odour Characteristic	Possible Source	Remarks
17 Aug 23	Rainy	OP1	15:03	28.0	N/A	N/A	N	0	N/A	N/A	N/A
17 Aug 23	Rainy	OP2	15:06	29.4	1.7	NE	N	0	N/A	N/A	N/A
17 Aug 23	Rainy	OP3	15:09	29.2	0.9	E	N	0	N/A	N/A	N/A
17 Aug 23	Rainy	OP4	15:10	29.1	1.6	SE	N	1	Leachate	LTP	N/A
17 Aug 23	Rainy	OP5	15:12	29.4	1.3	E	N	0	N/A	N/A	N/A
17 Aug 23	Rainy	OP6	15:15	30.6	1.8	SE	N	0	N/A	N/A	N/A
17 Aug 23	Rainy	OP7	15:17	30.6	2.5	SE	N	0	N/A	N/A	N/A
17 Aug 23	Rainy	OP8	15:20	32.8	3.5	SE	Y	1	Sludge	Sediment trap	N/A
17 Aug 23	Rainy	OP9	15:28	30.7	1.9	SE	Y	1	Landfill gas	Tipping area	N/A
17 Aug 23	Rainy	OP10	15:30	30.0	3.2	E	Y	1	Waste	Tipping area	N/A
17 Aug 23	Rainy	OP11	15:47	31.8	0.0	N/A	N	1	Waste	Tipping area	N/A
17 Aug 23	Rainy	OP12	15:45	29.4	1.5	SE	N	0	N/A	N/A	N/A
17 Aug 23	Rainy	OP13	15:44	29.5	0.0	N/A	N	0	N/A	N/A	N/A
17 Aug 23	Rainy	OP14	15:42	30.0	0.0	N/A	N	0	N/A	N/A	N/A
17 Aug 23	Rainy	OP15	16:00	30.7	0.0	N/A	N	0	N/A	N/A	N/A
17 Aug 23	Rainy	OP16	15:58	30.5	1.5	E	Y	0	N/A	N/A	N/A
17 Aug 23	Rainy	OP17	15:56	31.1	1.1	NW	Y	0	N/A	N/A	N/A