

Annex D6

Odour Monitoring Results

Table D6.1 Odour Monitoring Results

Date	Weather	Location	Time	Temperature (°C)	Wind Speed (m/s)	Wind Direction	From Project Site	Odour Intensity	Odour Characteristic	Possible Source	Remarks
9 Nov 23	Rainy	OP1	13:43	26.7	1.9	SW	Yes	0	N/A	N/A	N/A
9 Nov 23	Rainy	OP2	13:47	27.5	1.1	SW	Yes	0	N/A	N/A	N/A
9 Nov 23	Rainy	OP3	13:49	27.9	5.6	W	Yes	0	N/A	N/A	N/A
9 Nov 23	Rainy	OP4	13:51	26.9	2.8	N	Yes	1	Leachate smell	LTP	N/A
9 Nov 23	Rainy	OP5	13:53	26.7	4.0	NE	No	0	N/A	N/A	N/A
9 Nov 23	Rainy	OP6	13:57	26.9	2.9	N	No	0	N/A	N/A	N/A
9 Nov 23	Rainy	OP7	13:58	26.3	2.3	S	No	0	N/A	N/A	N/A
9 Nov 23	Rainy	OP8	14:02	27.7	2.8	NE	Yes	0	N/A	N/A	N/A
9 Nov 23	Rainy	OP9	14:05	29.4	0.0	N/A	No	0	N/A	N/A	N/A
9 Nov 23	Rainy	OP10	14:01	27.6	1.3	SE	No	0	N/A	N/A	N/A
9 Nov 23	Rainy	OP11	14:18	26.8	2.2	E	No	0	N/A	N/A	N/A
9 Nov 23	Rainy	OP12	14:15	27.9	2.2	E	No	0	N/A	N/A	N/A
9 Nov 23	Rainy	OP13	14:14	26.8	1.4	E	No	0	N/A	N/A	N/A
9 Nov 23	Rainy	OP14	14:12	26.4	0.0	N/A	No	0	N/A	N/A	N/A
9 Nov 23	Rainy	OP15	14:28	26.8	2.2	W	No	0	N/A	N/A	N/A
9 Nov 23	Rainy	OP16	14:29	25.9	6.2	N	Yes	0	N/A	N/A	N/A
9 Nov 23	Rainy	OP17	14:30	27.5	4.4	S	No	0	N/A	N/A	N/A