



ANNEX D6

ODOUR MONITORING RESULTS

TABLE D6.1 ODOUR MONITORING RESULTS

Date	Weather	Location	Time	Temperature (°C)	Wind Speed (m/s)	Wind Direction	From Project Site	Odour Intensity	Odour Characteristic	Possible Source	Remarks
20 Sep 24	Cloudy	OP1 ^(a)	13:58	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Not accessible
20 Sep 24	Cloudy	OP2	14:00	31.7	2.4	S	No	1	Grassy	Vegetation	N/A
20 Sep 24	Cloudy	OP3	14:06	32.1	1.3	S	No	0	N/A	N/A	N/A
20 Sep 24	Cloudy	OP4	14:09	32.2	3.0	E	No	0	N/A	N/A	N/A
20 Sep 24	Cloudy	OP5	14:12	32.2	1.6	E	No	0	N/A	N/A	N/A
20 Sep 24	Cloudy	OP6	14:15	32.4	0.7	SE	No	0	N/A	N/A	N/A
20 Sep 24	Cloudy	OP7	14:18	33.5	1.5	S	No	0	N/A	N/A	N/A
20 Sep 24	Cloudy	OP8	14:19	33.9	0.9	S	No	0	N/A	N/A	N/A
20 Sep 24	Cloudy	OP9	14:22	33.7	1.2	SE	Yes	0	N/A	N/A	N/A
20 Sep 24	Cloudy	OP10	14:28	33.1	1.7	E	Yes	0	N/A	N/A	N/A
20 Sep 24	Cloudy	OP11	14:33	32.3	2.1	SE	Yes	1	Waste smell	Cell 4X Tipping area	SENTx
20 Sep 24	Cloudy	OP12	14:42	31.7	1.8	SE	Yes	0	N/A	N/A	N/A
20 Sep 24	Cloudy	OP13 ^(a)	14:46	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Not accessible
20 Sep 24	Cloudy	OP14	14:46	30.8	3.9	SE	No	1	Soil smell	Restoration work	SENT
20 Sep 24	Cloudy	OP15	15:13	31.6	1.2	E	No	0	N/A	N/A	N/A
20 Sep 24	Cloudy	OP16	15:10	31.0	1.2	SE	No	0	N/A	N/A	N/A
20 Sep 24	Cloudy	OP17	15:07	31.1	2.1	SW	Yes	0	N/A	N/A	N/A

Note:

(a) OP1 and OP13 are not accessible due to the landscape reparation work and construction work respectively.