





ANNEX G1

LANDFILL GAS MONITORING
LOCATIONS FOR SERVICE VOIDS,
UTILITIES AND MANHOLES ALONG THE
SITE BOUNDARY AND WITHIN THE
SENTX SITE





WATER TANK

CONFERENCE ROOM
CAR PARK

6.00

5.00
0.00%

VEHICLE WASH FACILITY

Wheel Wash Bath

EQUIPMENT STORAGE AREA

MAINTENANCE BUILDING

LABORATORY

LABORATORY
GAS ROOM
CONTROL ROOM
WINS &
CONTROL ROOM

STORAGE

CAR PARK

UU08

UU19

UU18

UU17

UU15

UU09

UU10

UU16

UU20

UU21

UU26

UU22

UU23

UU24

UU25

UU14

UU13

UU12

UU11

UU27

UU28