



ANNEX G3

LANDFILL GAS MONITORING RESULTS

TABLE G3.1 LANDFILL GAS MONITORING RESULTS AT PERIMETER LFG MONITORING WELLS

Location	Water Level (mPD)	Methane (% (v/v))	Carbon Dioxide (% (v/v))	Oxygen (% (v/v))
LFG1	2.58	0.0	0.1	20.6
LFG2	2.63	0.0	0.2	20.2
LFG3	2.69	0.0	0.9	19.9
LFG4	2.56	0.0	0.2	20.2
LFG5	2.88	0.0	0.5	14.5
LFG6	2.65	0.0	0.2	20.4
LFG7	3.08	0.0	0.1	20.2
LFG8	2.98	0.0	0.1	20.4
LFG9	2.79	0.0	0.1	20.1
LFG10	2.46	0.0	0.1	20.3
LFG11	2.68	0.0	0.1	20.3
LFG12	2.58	0.0	0.1	18.3
LFG13	2.12	0.0	0.1	20.3
LFG14	2.33	0.0	0.1	20.3
LFG15	2.22	0.0	0.2	20.2
LFG16 ^(a)	N/A	0.0	0.3	18.5
LFG17 ^(a)	N/A	0.0	0.1	20.5
LFG18	3.4	0.0	0.2	20.4
LFG19	3.02	0.0	0.1	20.3
LFG20	3.28	0.0	0.2	20.4
LFG21	3.02	0.0	0.1	20.4
LFG22	2.93	0.0	0.2	20.3
LFG23	12.83	0.0	0.1	20.5
LFG24	6.26	0.0	0.1	20.9
GP1	Probe Bent	0.0	6.9	13.1
GP2 (shallow)	Probe Bent	0.0	0.9	18.3
GP2 (deep)	Probe Bent	0.0	2.5	15.0
GP3 (shallow)	Probe Bent	0.0	0.1	20.8
GP3 (deep)	Probe Bent	0.0	0.1	20.8
GP4 (shallow)	Probe Bent	0.0	1.2	18.9
GP4 (deep)	Probe Bent	0.0	1.6	19.4
GP5 (shallow)	Probe Bent	0.0	0.1	20.9
GP5 (deep)	38.6	0.0	0.1	20.9
GP6	36.83	0.2	0.1	18.7

Location	Water Level (mPD)	Methane (% (v/v))	Carbon Dioxide (% (v/v))	Oxygen (% (v/v))
GP7	26.13	0.0	0.2	18.2
GP12	2.25	0.0	0.2	20.7
GP15	2.67	0.0	0.1	20.1
P7	2.71	0.0	0.7	17.1
P8	2.73	0.0	0.6	20.0
P9	2.74	0.0	0.1	20.7

Note:

(a) The dip level of Monitoring well LFG16 and LFG17 could not be measured due to thick grass layer.

TABLE G3.2 LANDFILL GAS MONITORING AT SERVICE VOIDS, UTILITIES PITS AND MANHOLE

Location	Methane (% (v/v))	Carbon Dioxide (% (v/v))	Oxygen (% (v/v))
UU01	0.0	0.2	20.5
UU02	0.0	0.2	20.4
UU03	Voided due to latest site programme and on-going operation work		
UU04	0.0	0.2	20.4
UU05	0.0	0.2	20
UU06	0.0	0.2	20.2
UU07	0.0	0.2	20.4
UU08	0.0	0.2	20.2
UU09	0.0	0.2	20.3
UU10	0.0	0.2	20.3
UU11	0.0	0.2	20.2
UU12	Voided due to latest site programme and on-going operation work		
UU13	0.0	0.2	20.4
UU14	0.0	0.2	20
UU15	0.0	0.2	20.2
UU16	0.0	0.2	20.4
UU17	Voided due to latest site programme and on-going operation work		
UU18	Voided due to latest site programme and on-going operation work		
UU19	Voided due to latest site programme and on-going operation work		
UU20	0.0	0.2	20.4
UU21	0.0	0.2	20.3
UU22	0.0	0.2	20.3
UU23	0.0	0.1	20.3
UU24	0.0	0.1	20.4
UU25	0.0	0.1	20.3
UU26	0.0	0.1	20.3

Location	Methane (% (v/v))	Carbon Dioxide (% (v/v))	Oxygen (% (v/v))
UU27	0.0	0.1	20.4
UU28	0.0	0.1	20.3

TABLE G3.3 LANDFILL GAS BULK GAS SAMPLING MONITORING RESULTS

Parameters	LFG4	LFG6
Methane (% (v/v))	<0.020	<0.020
Carbon Dioxide (% (v/v))	0.133	0.111
Oxygen (% (v/v))	20.1	20.4
Nitrogen (% (v/v))	77.2	77.3
Carbon Monoxide (% (v/v))	<0.020	<0.020
Hydrogen (% (v/v))	<0.020	<0.020
Ethane (ppmv)	<1.0	<1.0
Propane (ppmv)	<1.0	<1.0
Butane (ppmv)	<1.0	<1.0

TABLE G3.4 FLAMMABLE GAS SURFACE EMISSION MONITORING RESULTS

Time	GPS Coordinates Latitude (N)	Longitude (E)	Weather Condition	Temperature (°C)	Wind Direction (Deg)	Wind Speed (m/s)	Monitoring Results (ppm)
------	---------------------------------	---------------	-------------------	------------------	----------------------	------------------	--------------------------

No flammable gas surface emission detected in the reporting period