





ANNEX G1

LANDFILL GAS MONITORING
LOCATIONS FOR SERVICE VOIDS,
UTILITIES AND MANHOLES ALONG THE
SITE BOUNDARY AND WITHIN THE
SENTX SITE





WATER TANK

COMPLETION OF THE ED. REPAIRS
CAR PARK

UU20

UU22
UU23

UU21

UU19

UU18

UU16

UU24
UU25

UU17

UU26

UU15

UU09

UU14

UU13
UU12

UU27

UU10

UU11

UU28

UU08

6.00

5.00
0.00%