



ANNEX D6

ODOUR MONITORING RESULTS

TABLE D6.1 ODOUR MONITORING RESULTS

Date	Weather	Location	Time	Temperature (°C)	Wind Speed (m/s)	Wind Direction	From Project Site	Odour Intensity	Odour Characteristic	Possible Source	Remarks
1 Aug 25	Sunny	OP1	14:05	27.2	1.1	NE	No	0	N/A	N/A	N/A
1 Aug 25	Sunny	OP2	14:08	25.2	2.8	SE	No	0	N/A	N/A	N/A
1 Aug 25	Sunny	OP3	14:10	25.5	1.2	SE	No	0	N/A	N/A	N/A
1 Aug 25	Sunny	OP4	14:11	25.7	2.3	SE	No	0	N/A	N/A	N/A
1 Aug 25	Sunny	OP5	14:14	25.6	1.3	SE	No	0	N/A	N/A	N/A
1 Aug 25	Sunny	OP6	14:15	25.5	1.8	SE	No	0	N/A	N/A	N/A
1 Aug 25	Sunny	OP7	14:17	25.9	0.5	SE	No	0	N/A	N/A	N/A
1 Aug 25	Sunny	OP8	14:19	25.8	2.3	SE	No	0	N/A	N/A	N/A
1 Aug 25	Sunny	OP9	14:22	25.8	1.5	SE	Yes	0	N/A	N/A	N/A
1 Aug 25	Sunny	OP10	14:24	25.4	1.6	SE	Yes	0	N/A	N/A	N/A
1 Aug 25	Sunny	OP11	14:28	24.9	3.2	SE	Yes	0	N/A	N/A	N/A
1 Aug 25	Sunny	OP12	14:35	24.9	3.2	SE	Yes	1	Waste smell	Cell 4X Tipping area	SENTx
1 Aug 25	Sunny	OP13	14:41	25.4	5.2	SE	Yes	1	Waste smell	Cell 4X Tipping area	SENTx
1 Aug 25	Sunny	OP14	14:38	26.1	4.9	SE	No	0	N/A	N/A	N/A
1 Aug 25	Sunny	OP15	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Not accessible
1 Aug 25	Sunny	OP16	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Not accessible
1 Aug 25	Sunny	OP17	14:52	N/A	1.5	S	No	0	N/A	N/A	N/A

Note:

(a) OP15 – OP16 are not accessible due to the safety considerations (slope reparation work).