


Annex G1

Landfill Gas Monitoring  
Locations for Service Voids,  
Utilities and Manholes  
along the Site Boundary and  
Within the SENTX Site





WATER TANK

CONFERENCE ROOM  
CAR PARK

6.00

5.00  
00%

VEHICLE WASH FACILITY

Wheel Wash Bath

STORAGE  
STORAGE

MAINTENANCE BUILDING

LABORATORY GAS  
CONTROL ROOM  
WINS & CO.

STORAGE

CAR PARK

UU08

UU19

UU18

UU17

UU15

UU09

UU10

UU26

UU16

UU21

UU20

UU22

UU23

UU24

UU25

UU14

UU13

UU12

UU11

UU27

UU28